Specifications

Environmont	Component Video (VPhPr) RGB Video (sync on green) 480i/n 720n		
	1080i/n		
Devices	DVD players satellite receivers plasma displays projectors monitors		
Devices	DvD players, satellite receivers, plasma displays, projectors, monitors,		
	supporting HDTV component video and/or stereo audio		
Transmission	Transparent to the user		
Bondwidth	Video (V): DC to 60 MHz 2 dP roll off		
Danuwiuui	Analog audio: 20 Hz to 20 kHz		
Maximum Innut			
Insertion Loss	0.1 dD for 0.1 MHz		
(V channel)	Gradually increasing to 2.5 dB over the frequency range		
(I thannel)	Less than 2 dB over the frequency range per pair of balung		
TUD	Less than 0.007% at 1 kHz		
Detum Loss (V chon1)	Less than 0.00/% at 1 KHZ		
Common Mal D i di	Greater than 15 dB over the frequency range		
Common Mode Rejection	-55 dB at 0.1 MHz		
Katio (Y channel)	Gradually increasing to -20 dB at 60 MHz		
Ground Loop Coupling	Proprietary technique helps eliminate hum bars		
(GLC)	US Patent Pending		
Max. Distance via	Video: 480i/p: 1,000 ft (305 m). 720p and 1080i/p: 500 ft (152 m)		
Cat 5E/6 UTP/STP Cable	Stereo Audio: 3,250 ft (1 km)		
Cable:	24 AWG or lower solid copper twisted pair wire		
Cat 5E/6 UTP/STP	Impedance: 100 ohms at 1 MHz		
	Maximum capacitance: 20 pf/ft		
	Attenuation: 6.6 dB/1,000 ft at 1 MHz		
Cable: RCA	Impedance: 75 ohms at 1 MHz		
Connectors Video	Three (3) RCA-M connectors: Green (Y), Blue (Pb), Red (Pr) on 6"		
	leads. RCA shields are on common ground.		
	RJ45 Shielded for twisted pair.		
Connectors Audio	Two (2) RCA jacks for analog audio		
	RCA shields are on common ground		
Pin Configuration	Use EIA 568 A or B wiring standard and straight-through wiring		
Reverse polarity sensitive			
Compatibility	Not compatible with 500050/51/52/53/54/55/56/57		
Temperature	Operating: 0° to 55°C		
	Storage: -20° to 85°C Humidity: Up to 95% non-condensing		
Enclosure	ABS fire retardant plastic		
Dimensions	2.40" x 2.25" x 1.00" (6.10 x 5.72 x 2.54 cm) plus 6" (15 cm)		
	cable lead for video		
Weight	4.4 oz (122 g)		
Compliance	FCC, CE		
Warranty	Lifetime		
Order Information	500058 Component Video/Stereo Audio Balun		



Component Video / Stereo Audio Balun 500058

Quick Installation Guide

Overview

The Component Video/Stereo Audio Balun (500058) allows one component video (YPbPr or RGB) signal and one (1) Stereo Audio channel to be transmitted via a Cat 5E/6 twisted pair cable for more cost-efficient cabling. The product features Ground Loop Coupling (GLC) to help eliminate "hum" bars. Used in pairs, the Component Video/Stereo Audio Balun supports high-definition resolution and true left/right stereo audio for hi-fidelity commercial and residential AV applications. *The 500058 is not compatible with part numbers 500050/51/52/53/54/55/56/57*.

E-mail: videoease@muxlab.com URL: www.muxlab.com

Installation

One (1) pair of baluns is needed to complete one component (YPbPr/RGB) connection via a Cat 5E/6 twisted pair. To install the baluns, perform the following steps:

1. The pin configuration must be according to EIA 568, either A or B and wired straight-through (no crossover).



2. Plug one (1) balun into the component video output of the audio-video source according to the color code of the RCA cable leads and jacks.



- 3. Repeat step 2 for the second balun at the display side.
- 4. Complete the connection between the two baluns, using standard Cat 5E/6 twisted pair cable and connecting hardware, terminated on RJ45 plugs at both ends, ensuring that there are no split pairs or taps.
- 5. If Stereo Audio is to be connected (optional), connect left/right RCA jumper cables between the balun and the stereo audio equipment at both ends.
- 6. Power-on the component video equipment. Check the image quality and refer to the troubleshooting table below if the image quality is unsatisfactory. The following diagram shows a typical installation.



Troubleshooting

The following tables describe some of the symptoms, probable causes and possible solutions in respect to the installation of the Component-Stereo Balun:

Video Symptom	Probable Cause	Possible Solutions
No video	No continuity in video link	Verify cable continuity between pairs of baluns.
	Power off	Check power supplies of video equipment.
	Improper connection and/or	Check that baluns are connected to correct video
	swapped pair	inputs and outputs.
Unusual colors	Reversed polarity	Check wiring and ensure straight-through polarity
Background pattern	EMI interference	Identify possible radiating frequency sources (<i>i.e.</i> wireless LANs, switching power supplies). Try to isolate them from the video connection. Use shielded twisted pair grounded at both ends.
Smearing	Exceeded distance or faulty UTP cable or crimping	Verify cable. Use higher grade cable if necessary.
Weak contrast	Exceeded distance	Verify cable grade. Use higher grade cable if necessary. Increase contrast on monitor.
	Unusual link attenuation	Verify cable distance using ohmmeter or cable tester.
Image not stable	Defective link or equipment	Verify video equipment interface integrity.
Slowly moving noise or horizontal bars	Missing ground (GND)	Ensure that at least the video source or display has a 3-prong AC power plug, grounded antenna coax cable or any grounded device in the link that can help clear up the interference. A single ground in the link is recommended.
Horizontal hum bars moving slowly	Substantial cross-talk between multiple video sources	Consecutively turn off other video sources to determine which video source is the cause of interference.
Snowy picture	Distance is near limit	Verify cable grade. Use higher grade cable if necessary. Reduce color intensity at monitor.
Poor image	EMI interference	Check that wiring is not too close to transformers, ballast's, air conditioners, RF transmitters or similar equipment. Use of power conditioner may help.

Audio Symptom	Probable Cause	Possible Solutions
No audio	Missing continuity in the circuit	Verify and correct the circuit.
	Power-off	Check power supplies of audio equip.
Missing channel	Cabling problem between the sound source and the audio speakers	Check audio speaker cabling.
Noise, static	EMI interference	Check that wiring is not too close to transformers, ballasts, air conditioners, RF transmitters or similar equipment.
	Distance exceeded or unusual cable attenuation	Check cable distance and cable grade. Also lifting GND on transmitter or receiver side may help.

If you still cannot diagnose the problem, please call MuxLab Customer Technical Support at 877-689-5228 (toll-free in North America) or (+1) 514-905-0588 (International).